



**World Automotive Headquarters:**

The Sherwin-Williams Automotive Finishes Corp.  
 4440 Warrensville Center Road  
 Warrensville Heights, OH, USA 44128-2837

**Customer Service:**

1-800-SW-ULTRA (800-798-5872)  
[www.sherwin-automotive.com](http://www.sherwin-automotive.com)

Sherwin-Williams Plastics Systems					
Plastic Primer	Primer Surfacer		Primer Sealer	Basecoat	Clearcoat
<a href="#">UPO7228 Low VOC Adhesion Promoter</a> <a href="#">UPO7229 National Rule Adhesion Promoter</a>	<a href="#">P30 SpectraPrime™</a>  <a href="#">P27 2.1 Primer</a>		<a href="#">P30 SpectraSeal</a> <a href="#">P27 2.1 Sealer</a>	<a href="#">Ultra 7000® Basecoat</a>  AWX  Ultra 9K Basecoat(Coming Soon!)	<a href="#">HPC15 HP Process Clearcoat</a> <a href="#">HPC21 Low VOC HP Process Clearcoat</a> <a href="#">CC930 Ultra 7000® Clearcoat</a> <a href="#">CC931 Ultra 7000® Clearcoat</a> <a href="#">CC939 Ultra 7000® Clearcoat</a> <a href="#">CC950 Ultra 7000® Clearcoat</a> <a href="#">CC927 VOC Matte Clearcoat</a> <a href="#">1100755 Elegance Clear</a>

Sherwin-Williams Metal Systems		Steel and Aluminum				
Etch Primer	Primer Surfacer		Primer Sealer	Basecoat	Clearcoat	
<a href="#">E2G970 - 1K Lead/Chrome Free Etching Primer</a> <a href="#">NP75 Direct to Metal (DTM) Primer Surfacer</a> <a href="#">PE995 Etch Primer</a>	<a href="#">P30 SpectraPrime™</a> <a href="#">NP75 Direct to Metal (DTM) Primer Surfacer</a> <a href="#">P27 2.1 Primer</a>		<a href="#">P30 SpectraSeal</a> <a href="#">P27 2.1 Sealer</a>	<a href="#">Ultra 7000® Basecoat</a>  AWX  Ultra 9k Basecoat(Coming Soon!)	<a href="#">HPC15 HP Process Clearcoat</a> <a href="#">HPC21 Low VOC HP Process Clearcoat</a> <a href="#">CC930 Ultra 7000® Clearcoat</a> <a href="#">CC931 Ultra 7000® Clearcoat</a> <a href="#">CC939 Ultra 7000® Clearcoat</a> <a href="#">CC950 Ultra 7000® Clearcoat</a> <a href="#">CC927 VOC Matte Clearcoat</a> <a href="#">1100755 Elegance Clear</a>	



To Meet Ford WSS-M2P-100D Specifications, a hardener or activator must be added to the basecoat

Ford recommends final coat of clearcoat must cover the entire repair panel.

Please refer to product data sheets for technical information.